

Message Text

UNCLASSIFIED

PAGE 01 QUITO 00458 222238Z

73

ACTION OC-06

INFO OCT-01 ARA-10 ISO-00 CCO-00 FBO-01 /018 W

----- 053094

P R 222131Z JAN 74

FM AMEMBASSY QUITO

TO SECSTATE WASHDC PRIORITY 9761

INFO AMEMBASSY LA PAZ

AMCONSUL GUAYAQUIL

UNCLAS QUITO 0458

FOR FBO, RCO

E.O. 11652: N/A

TAGS: ASUP, EC, COM

SUBJECT: EPABX INSTALLATION AND REPAIR - AMBASSADOR'S OFFICE

REF: A) STATE OM DTD 5 OCT 73; B) STATE 013260; C) QUITO 389

1. POST HAS TAKEN ACTION ON TECHNICAL ADVICE PROVIDED REFTEL (B) BUT WITH LIMITED SUCCESS. FUSES IN 301A2 SYSTEM CONTINUE TO BURN OUT.

2. POST ELECTRICIAN WILL TONIGHT TRY 230B TELEPHONE UNIT FROM POLITICAL SECTION SYSTEM TO CONFIRM WHETHER DAMAGE TO EXECUTIVE SUITE 230B UNIT IS MAIL PROBLEM. RESULTS OF THIS TESTS WILL BE PASSED TO OC.

3. DUE TO RECONFIGURATION OF EXECUTIVE AREA OFFICES AND CONTINUED PROBLEM WITH 301A2 SYSTEM POST REQUESTS FUNDING AND PROCUREMENT OF 513A3W KSU SYSTEM.

4. REF A INDICATES SECRETARIAL SYSTEM FOR B&M SECTION HAS BEEN FUNDED AND WILL BE SHIPPED IN THE IMMEDIATE FUTURE. POST COULD USE SAID EQUIPMENT IN EXECUTIVE AREA UNTIL FUNDING FOR ITEM MENTIONED IN PARA 3 COULD BE CONSIDERED.

5. POST UNDERSTANDS FURTHER THAT TECHNICIAN MINATRE MAY PRESENTLY BE ON TDY LA PAZ. MINATRE WELL ACQUAINTED WITH UNCLASSIFIED

UNCLASSIFIED

PAGE 02 QUITO 00458 222238Z

QUITO EPABX AND COULD PROVIDE REQUIRED EXPERTISE TO SOLVE OUR

PROBLEMS.

6. PLEASE ADVISE.
BREWSTER

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 JAN 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 22 JAN 1974
Decaption Date: 01 JAN 1960
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Authority: n/a
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1974QUITO00458
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Film Number: n/a
From: QUITO
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1974/newtext/t19740124/aaaaawta.tel
Line Count: 65
Locator: TEXT ON-LINE
Office: ACTION OC
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: A) STATE OM DTD 5 OCT 73; B) STATE 0, 13260; C) QUITO 389
Review Action: RELEASED, APPROVED
Review Authority: shawdg
Review Comment: n/a
Review Content Flags:
Review Date: 04 OCT 2002
Review Event:
Review Exemptions: n/a
Review History: RELEASED <04 OCT 2002 by elyme>; APPROVED <20-Nov-2002 by shawdg>
Review Markings:

Declassified/Released
US Department of State
EO Systematic Review
30 JUN 2005

Review Media Identifier:
Review Referrals: n/a
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
Secure: OPEN
Status: NATIVE
Subject: EPABX INSTALLATION AND REPAIR - AMBASSADOR'S OFFICE
TAGS: ASUP, ACOM, EC
To: STATE
Type: TE
Markings: Declassified/Released US Department of State EO Systematic Review 30 JUN 2005